

Brushes on table  
and supports



Front Protection  
with Light Guards



Chute for small pieces



Adjustable Goniometer  
for angle cutting



Transport Belts



Extended Front  
Supports



2-axis Back Gauge,  
X1-X2, for angle  
cutting

